



Service information

Reference no.: SDA_104800

Symptom

Strange noise after coffee production.

Cure

INFO:

While the Brew Unit goes back in home position after coffee product dispensing, it can happen that in the final stage of movement it generates a strange noise. This issue is present on old appliances updated with the software 01.09.08 or a higher version, when they are repaired by the Service Centers.

CURE:

Re-program the machine with the new software version 01.10.04.

In detail:

Removed brew unit slowdown phase because in some conditions it can cause noises.

HISTORY:

04/04/2014 - First Release