



**Service information**

**Reference no.: SDA\_105005**

**Symptom**

Brew unit cannot be placed back in the machine.

**Cure**

**INFO:**

If the consumer remove the brew unit, before the machine is in home- position, he cannot insert it again because the machine doesn't make the auto-reset if the brew unit is not in the seat.  
This problem exists only with the new software (00.02.06).

**CURE:**

Re-program the machine with the new software version 00.02.09

**HISTORY:**

13/05/2014 - First Release