



Service information

Reference no.: SDA_107986

Symptom

Brushes for FC7070/ 7080/FC7088/FC7090

Cure

SYMPTOM:

When Brushes need to be replaced, the newest Brushes need to be used together with the new Brush Coupling Assy

Codes:

Brush assy 4322 005 36041
Brush coupling assy 4322 005 35991

This combination can be used for FC7080, FC7088 and FC7090 but also for all FC7070-models

REMARK / IMPORTANT :

only use these brushes in combination with the Brush coupling assy for FC7070 !!!