



Service information

Reference no.: SDA_109150

Symptom

Issue with metal boiler pins

Cure

INFO:

A quality issue with the metal boiler was discovered. the element connecting pins can be loose. Before installation of a new boiler the pins should be checked for tightness. A rotation of + and - 5 degrees is acceptable. Also the clicking noise the pins can make while rotating is acceptable.

REMARKS:

- 23-02-2015: Initial version.