



Service information


Reference no.: SDA_109307

Symptom

White Support boiler in GranBaristo family.

Cure

INFO:From serial TU901446163585 you may see the white boiler support (Image1). It has been temporarily introduced to counteract the premature wear of the piston seals.



CURE:

In case of replacement the support of white color order cod. 421944032332 NEU PISTON UNIT UPPER PART SUPP.V3 CST

ADDITIONAL INFORMATION:

SERIAL NUMBER (First serial where solution has been implemented in production):
From s.n. TU901446163585

IPM NUMBER (Philips Integrate Problem Management documentation reference number):
None.

FAQ NUMBER (for Call Center reference):
None.

INFORMATION FOR CALL CENTER:
None.

INFORMATION FOR CONSUMER:
None

HISTORY:
03/02/2015 - First Release