



**Service information**

**Reference no.: SDA\_109905**

**Symptom**

MANDATORY: Steam-out in Philips 2000 and XSmall Puro (without steam tube).

**Cure**

**INFO:**  
Steam-out procedure.

**CURE:**  
To make the Steam-out Philips 2000 and Xsmall Puro (without steam tube), proceed as explained in the attached sheet.

**ADDITIONAL INFORMATION:**

**SERIAL NUMBER (First serial where solution has been implemented in production):**  
None

**IPM NUMBER (Philips Integrate Problem Management documentation reference number):**  
105445

**FAQ NUMBER (for Call Center reference):**  
None

**INFORMATION FOR CALL CENTER:**  
None.

**INFORMATION FOR CONSUMER:**  
None.

**HISTORY:**  
15/04/2015 - First Release