



**Service information**

**Reference no.: SDA\_111084**

**Symptom**

Attention on HR202\* blender Motor&Housing&Bottom matching principle

**Cure**

From WK1344, the Motor (996510070324) must use with Housing (996510073765) and Bottom (996510073764) together. The Housing (996510063162) and Bottom (996510063158) are not valid for HR202\* motor anymore.