



Service information

Reference no.: SDA_111759

Symptom

PCB's of SmartPro Compact, SmartPro Active

Cure

SYMPTOM:
Wrong codes for PCB's for SmartPro Compact and SmartPro Active.

CURE:
The new 12NC's have been added to the Sboms and Service Manuals.
See overview for the correct 12NC's :

CTN	12NC of PCBA
FC8603/82	432200625801
FC8700/01	432200625811
FC8700/71	432200625811
FC8700/81	432200625821
FC8700/82	432200625821
FC8710/01	432200625831
FC8710/81	432200625841
FC8710/82	432200625841
FC8810/01	432200625851
FC8810/81	432200625861
FC8820/81	432200625871
FC8820/82	432200625871
FC8820/01	432200625881

These new PCB's are available per wk. 1541

INFO:
When the PCB's have been replaced, the callibration should be done as indicated in the enclosed instruction.