



Service information

Reference no.: SDA_112059

Symptom

Loss water, from the solenoid valve of Granbaristo.

Cure


INFO:

To avoid leakage due to incorrect assembly of the solenoid valve on GranBaristo (Image1), only the solenoid assembly will be available.



CURE:

Order the cod. 421944033041 SOLENOID VALVE V2 CST 24V ASSY (Image 2).



ADDITIONAL INFORMATION:

SERIAL NUMBER (First serial where solution has been implemented in production):
None.

IPM NUMBER (Philips Integrate Problem Management documentation reference number):
109750

FAQ NUMBER (for Call Center reference):
None.

INFORMATION FOR CALL CENTER:
None.

INFORMATION FOR CONSUMER:
None.

HISTORY:

09/11/2015 - First Release