



**Service information**

**Reference no.:** SDA\_113911\_E97\_G\_B\_HOUSINGPART

**Symptom**

Improved bottom housing does not fit anymore


**Cure**

**INFO:**


The improved bottom housing part 996510064773 used in HD776x does not fit on top housing part 996510064758 used in HD7761 & HD7762.

**CURE:**

Modify (cut 2 rims, see pictures below) bottom housing part 996510064773 to make it fit again on the 996510064758 used in HD7761 & HD7762.



9965 100 64773 - Bottom housing



**ADDITIONAL INFORMATION:**

IPM NUMBER (Philips Integrate Problem Management documentation reference number):  
IPM-119152

FAQ NUMBER (for Call Center reference):  
None

INFORMATION FOR CALL CENTER:  
None

INFORMATION FOR CONSUMER:  
None

HISTORY:  
27-06-2016 - First Release