



Service information

Reference no.: SDA_113915

Symptom

Alarm for "Close Service Door" doesn't work.

Cure

List of Symptoms:

- Alarm does not show up if Service Door is opened
- Alarm "close the service door" is always on (Image 01).

Cure:

In all Intelia, Intuita Moltio and Gaggia Naviglio machines a possible leakage of the solenoid valve can cause an oxidation of door microswitch:

Image 01



Actions: After repairing/replacement of the solenoid valve, order the microswitch including the cable (assy. Image 2)
Code: 421946000111 DOOR MICROSWITCH V3 NPR UL ASSY

Image 02



ADDITIONAL INFORMATION:

SERIAL NUMBER (First serial where solution has been implemented in production):
None

IPM NUMBER (Philips Integrate Problem Management documentation reference number):
None

INFORMATION FOR CONSUMER:
None

HISTORY:
27/06/2016 - First Release