

Service information

Reference no.: SDA_75961

Symptom

Aplliance does not start or suddenly stops during operation.

Cure

Info: The switch on the circuit board is open and might be melted somewhat.

Cure: Replace the complete circuit board service code 4322 006 23880

