



Service information

Reference no.: SDA_77496


Symptom

Hinge-joint broken off from brewhead Senseo latte select.

Cure

INFO:
Hinge-joint is broken off from brewhead Senseo latte select.

CURE:
Replace complete brewhead unit, see picture:



HD7850/8x => 4222 259 7480
HD7850/8x => 4222 259 42894
HD7852/5x => 4222 259 43844