



Service information

Reference no.: SDA_78482

Symptom

updated Blender Jar does not fit to the Housing due to techn change on Blender Jar (4203 035 88630)

Cure

till Production date 1002: you have to exchange also housing in case of claim on Blender Jar

from Production date 1003: onwards: you have only to change the Blender Jar (without Housing) => compability of Housing and Blender jar is given.

see also atatched service manual HR7770/00