Reference no.: SDA\_78805

## Service information

## **Symptom**

Mains switch does not operate

## Cure

INFO:

 $From \ market \ returns \ it \ became \ clear \ that \ the \ mains \ switch \ gets \ damaged \ usung \ too \ much \ force \ on \ the \ on/off \ button!$ 

Cure

Appliances are from now on equipped with a protective ring (see attached image). If this ring is missing it must still be placed as modification. Sparepart code 4222 459

