



Service information

Reference no.: SDA_81122

Symptom

GC8220 soleplate cover unavailable.

Cure

INFO:

The blue soleplate cover used in GC8220 is no longer available.

CURE:

The closest alternative available is the purple cover.

The purple cover however creates an undesirable color contrast against the blue color in the rest of the product.

To prevent the color contrast, please change the purple cover together with purple inlay & purple water tank.

Service code of Purple cover: 4239 026 30450

Service code of Purple inlay: 4239 026 30460

Service code of Purple water tank: 4239 021 46670

REMARK:

The purple parts are in fact used in GC8325. You can refer to GC8325 service manual.

Change inlay, cover & water tank to purple.

This helps to remove the color contrast between blue & purple.

