



Service information

Reference no.: SDA_81255

Symptom

There is steam leakage from steam tank cap for my steam station

Cure

Info: Applicable for GC6100 and GC6300 series

Other possible symptom:



Degradation of plastics

Reason for Steam leakage:

1. Sealing ring of steam cap worn out/ torn
2. Steam cap not tighten
3. Pressure control vl
4. Solid content inside boiler too high due to no rinsing/ descale. This results in foaming and calc accumulation on safety valve.

This leads to safety valve opening due to poor sealing.

Cure:

Replacement of steam filling cap. In the case of plastics housing damage, this needs to be replaced.