



Service information

Reference no.: SDA_81753

Symptom

Word marks comes loose from Lid panel.

Cure

INFO:

Word marks glued on the aluminum LID COVER from Senseo HD7835 can be easily removed.

Production batch WK1029 till WK1031 are affected.

90% of the batch are reworked but 10% of the appliances are in the field which could be returned by this reason.

See pictures for the symptom:



CURE:

Exchange complete brewchamber assy 422225948362