

**Service information**

**Reference no.: SDA\_81999**

**Symptom**

Rear wheels are creaking.

**Cure**

**INFO:**

For these types the rear wheels tend to creak due to molding issue (Shape of axle hole). This was solved from week 1030 on.

**CURE:**

Replace the wheels pos.43 (note: order 2 times since only one wheel will be delivered for these codes):

4222 459 47401 Rear wheel Red (1x)

4222 459 47411 Rear wheel Black (1x)

4222 459 47421 Rear wheel Green (1x).

