



Service information

Reference no.: SDA_82729

Symptom

Service part unavailable

Cure

INFO:

After optimization of the Garment Care spare part supply, some parts are removed from the service parts list.

CURE:

Please order assembly modules in which the affected spare parts are embedded. Kindly refer to attached Excel file for respective replacement modules of the affected spare parts.

REMARKS:

The affected service manuals will be revised to reflect the modified service parts list.

HISTORY:

Revision 16 Nov 2010: Attachment updated to reflect a change in the replacement part of 4239 022 58590 (Safety valve sealing ring). The new replacement part is [423901558201 \(O ring\)](#).