



Service information

Reference no.: SDA_84443

Symptom

Poor stability of milk carafe in Syntia Cappuccino

Cure

INFO:

Poor stability of milk carafe in Syntia Cappuccino line till the serial number TU901039054940.

CURE:

Replace the drip tray grate (image 1) by the kit code 20006952 built-up of new grate with two stoppers for giving more stability to milk carafe (image 2 and 3) and of instruction sheet for correct carafe placement.

