

Reference no.: SDA_84894



Service information

Symptom

Telescopic tube is not working anymore

Cure

INFO: Telescopic Tube is not working anymore.

CURE: Improvement has been done that problem will not occur anymore, implementation per november 2010 in production. (See attachment).

REMARKS : for replacement please use the telescopic tube, produced after November 2010.

See IPM 61177