

Service information

Symptom

Reference no.: SDA_85097

The appliance switches on automatically!

Cure

INFO: Consumers complains that the Senseo machine automatically switches on without consumer action.

CURE: Software has been made more robust. Exchange PCB 422225945043