



**Service information**

**Reference no.: SDA\_85386**

**Symptom**

Mandatory steam boiler thermostat replacement in Exprelia

**Cure**

INFO:

In Exprelia line replace two thermostats up to serial number **TU901107022155**.

CURE:

**Mandatory intervention required:** in all the Exprelia line coffee machines, that return to workshop for any reason, replace two thermostats of 175°C (part code 12001034) on the steam boiler by two thermostats of 190°C, part code 12001033.