



Service information

Reference no.: SDA_86702

Symptom

Exhaust grill is getting loose during cleaning a certain time


Cure

INFO: During the cleaning it can happen that Exhaust grill plops out because of the temperature.

CURE: Construction has been changed so that this problem will not occur again.

REMARK: When problem occurs : exhaust grill needs to be replaced by new one, 12 NC: 4222 459 47871

See picture : left is old grille / right is new



grille