

Reference no.: SDA_86737

Service information

Symptom

Leakage from safety valve's plastic pipe fitting connection

Cure

INFU: Leakage from safety valve's pipe fitting connection in Royal, Spidem My Coffee, Xsmall, Syntia, Gaggia Brera, Gaggia Platininium and Unica, Odea, Incanto, Cafè Crema and Espresso Italiano.

CURE:
Replace the original safety valve, that has a plastic pipe fitting connection, by the safety valve with brass pipe fitting, part code 11004689.