



### Service information

Reference no.: **SDA\_86784**

#### Symptom

Coffee volume in Spain, Brazil and Argentina specific models of Senseo

#### Cure

##### INFO:

it has been decided to standardize the in-cup volume of coffee for Spain,- Brazil,- and Argentina specific models.

##### CURE:

This means the in-cup volume for Spain wil be increased from 50 to 60ml. In parallel the Podholder will be changed over from an Espresso type of pod-holder to a generic low-volume type of pod-holder

- 4222 259 44320 --> 4222 259 38970
- 4222 259 44330 --> 4222 259 39030
- 4222 259 44340 --> 4222 259 38960
- 4222 259 44350 --> 4222 259 39020
- 4222 259 47910 --> 4222 259 40410
- 4222 259 47920 --> 4222 259 40420
- 4222 259 48560 --> 4222 259 44210
- 4222 259 48570 --> 4222 259 44220

##### REMARKS:

All change will be refelected in the AtYourService portal  
The change is scheduled to be implemented per WK1125