



Service information

Reference no.: SDA_87095

Symptom

SCF870 steam blender Crack on main unit shaft.

Cure

INFO:

SCF870 steam blender Crack on main unit shaft

At the Baby Steam Blender SCF870 it could happened that small crack lines can occur on the main unit shaft (see picture).

CURE:

The product was optimized to this failure product up from production cw40 2010.

This failure should not occur anymore or only very rare in single cases.

In case of this failure replase the power unit.

REMARK: -

IRIS CODE:160; 161

HISTORY: