



**Service information**

**Reference no.: SDA\_87736**

**Symptom**

Mandatory insertion of protection to pump's tube in Xsmall

**Cure**

**INFO:**

Xsmall up to serial number TW901120258927.

Leakage under the device caused by the pump's silicone tube damaged in contact with the plastic support.

**CURE:**

In all the Xsmall up to serial number TW901120258927, that return to workshop for any reason, the red protection (image 1), part code 11027130, must be added to the pump's silicone tube.

