



Service information

Reference no.: SDA_89810

Symptom

Mandatory Replacement Ulka pump

Cure

INFO:
Possible fault in the component's operation over time in the machines below:
10003326 DO PSA SYNTIA CAPP.SS 230/SCH WE
10003357 DO GAG BRERA LED GMS 240/UK
10003370 DO GAG BRERA LED GMS 240/AUS
10003614 DO PSA SYNTIA FOCUS BLK BLK 220/CHN
10003662 DO GAG BRERA LED BLK 230/CH
Production week : 34/2010 (check serial number: TU901034xxxxxx)

CURE:
Replace the ULKA pump if the production's date component corresponds to 26/5/2010.
(see attached image 1)

