



Service information

Reference no.: SDA_90661

Symptom

Royal Line (Eng).

Cure

INFO:

01. Type of machine: Royal line
Content: **Failure on the temperature sensor**
02. Type of machine: Royal Cappuccino 2002 (Redesign)
Content: **Motor BG turn very slow**
03. Type of machine: Royal line
Content: **Connection to Cappamore with o-ring 142270200**
04. Type of machine: Royal line
Content: **Cover of the coffee dispenser**
05. Type of machine: Royal Office Upgrade
Content: **"sensor error 2"**
06. Type of machine: Royal line
Content: **Connectors CPU**
07. Type of machine: Royal Cappuccino / Professional
Content: **Washing after decalcification program**
08. Type of machine: Royal Professional with red silicon tube
Content: **No milk foam from the Cappuccinatore**

CURE:

Please see attached file in Eng.