



**Service information**

**Reference no.: SDA\_90669**

**Symptom**

For Talea and Odea Line (Eng).

**Cure**

**INFO:**

**01. Type of machine:** Talea Ring / Ring Plus / Touch

Content: **Cleaning program after switch on**

**02. Type of machine:** Talea Line

Content: **Whistle from the power-board**

**03. Type of machine:** Milk Island

Content: **Bad or no milk foam**

**04. Type of machine:** Milk Island

Content: **Milk Island fill by water from the machine**

**05. Type of machine:** Odea/Talea Line

Content: **Technical changes**

**06. Type of machine:** Odea

Content: **Hotwater/steam valve for exact position**

**07. Type of machine:** Talea Ring Plus until 9007SA40295390

Content: **Wrong display showing letters „ü“**

**08. Type of machine:** Talea Touch

Content: **Error 06 – Tab Board**

**09. Type of machine:** Talea Giro / Odea Giro - Go

Content: **Sensor Residual water tank**

**10. Type of machine:** Odea Giro / Go

Content: **CPU with connector for different versions**

**11. Type of machine:** Talea Giro / Gaggia Event

Content: **CPU with connector for different versions**

**12. Type of machine:** Odea / Talea

Content: **problem in case of wrong software**

**13. Type of machine:** Odea Line

Content: **splashing coffee dispenser**

**14. Type of machine:** Odea / Talea

Content: **different failures**

**15. Type of machine:** Talea /Odea

Content: **New – old filter 20000400 in the BG**

**16. Type of machine:** Talea Touch Plus (new sw/red Display)

Content: **Software update**

**17. Type of machine:** Talea /Odea

Content: **noise from the pump**

**18. Type of machine:** Talea / Odea

Content: **defect gear of the BG motor**

**CURE:**

**Please see attached file in Eng.**

**History:**

23/07/2013 - Second Review - Includes SDAs 80818 -81286 -80579

20/11/2011 - First Release