



Service information

Reference no.: SDA_90868

Symptom

Appliance works for 2 seconds, then nozzle/brushes stops

Cure

INFO:

A problem with the FC7070 AquaTrio appliance has been identified, the symptom described is that the appliance will continuously lock in the Active Protection System (APS) after only 2 seconds of operation. In the drivetrain driving the brushes there are magnets to detect the rotation and speed of the brushes, because of an improper fixation method used **before WK1145**, the magnets can come loose. When either one of the magnets is no longer present, the appliances sensors get falsely triggered.

CURE:

Replace the drivetrain (**4322 005 26721**) of the appliance. Service stock has been checked and found to be produced >WK1145.

REMARKS:

Only appliances produced before WK1145 could suffer from this defect, when you encounter an appliance produced after WK1145, the BU would like to be informed by IPM.