



Service information

Reference no.: SDA_91401

Symptom

Spouthousing Latte Select HD7850 No Longer Available

Cure

INFO:
The spouthousing of HD7850 models is no longer available from the supplier.

CURE:
It has been replaced with the lighter coloured model of the HD7852 High-end Latte Select, (422225945440) when this spouthousing needs replacement we advice to also replace the spouthousing cover (422224761740) to keep the colour matching.

REMARKS:
- 14-02-2012: Initial version