



Service information

Reference no.: SDA_91607


Symptom

Spare filter door Grind & Brew

Cure

INFO:

Due to a supplier error the initial shipments of the spare filter door for HD7740, HD7751 & HD7753 have been supplied with some additional components (cover for the hinge axle and two screws). These parts are officially no part of the spare part assembly, and will therefore no longer be supplied in new shipments from the supplier to DHL.



CURE:

When you receive the spare from DHL, please transfer the cover and screws from the original filterholder to the new spare filterholder.

REMARKS:

- 24-02-2012: Initial version.