



Service information

Reference no.: SDA_91740

Symptom

PCBA 422225934898 & 422225940310 are NLA

Cure

INFO:

DHL informed us that 422225934898 & 422225940310 are No Longer Available from the supplier.

CURE:

I have changed both over to 422225952711, which is compatible but with limitations. The light rings around the one-cup and two-cup button will no longer be functional (no visual indication anymore). Also only the high-level (2-cups) hall sensor can be connected to the board, as there is only one connector for a hall sensor. the other Hall sensor may be taken out or left in place, unconnected. The result will be a fully functional machine, but without the water level feedback in the buttons of the appliance, equal to a regular Senseo New Generation or Senseo 2.

REMARKS:

01-03-2012: Initial version