Service information


Reference no.: S **Symptom**

Brewhead detection sensor snapped off

Cure

INFO:
We get complaints from the fiels stating that after repair of an appliance the functional check fails, or the appliance comes back for repeat repair because the unit does not work.

CURE:
It has been observed that the sensors' fixation is not very securely. When opening the appliance it can fall out easily, when it is reinstalled incorrectly the indicated piece of plastic can easi reinstalling the sensor incorrectly can be done quite easily. I will add the component (422224761601)to all partslists of Senseo Quadrante.



REMARKS: 01-03-2012: Initial version