



#### Service information

Reference no.: SDA\_91928

### Symptom

Changing the front cover is very hard

### Cure

#### INFO:

During training it was discovered that removal of the front cover (for instance when the notch activating the hood switch has broken off) is very hard. This is caused by the fixation of the Hood side panels (pos. 22 & 39) on the hinges.

#### CURE:

To replace the Hood assy more easily, you should first use a sharp tool to remove this fixation from the hinge of the hood. This is no problem, as the notches are part of the hood, not the nozzle and the hood will be discarded since this was the defective part in the first place. Then the Hood side panels (grey in the picture below) will be removable without breakage. The fixation notches are indicated in the picture below (in blue):



#### REMARKS:

- 14-03-2012 Initial version.