



Service information

Reference no.: SDA_92025

Symptom

Button for Exprelia

Cure

INFO:

A serigraphy process error has caused in some machine of the Exprelia line a dissolving problem of the serigraphy keys after a prolonged use. The products involved on this issue are those from serial number TU901030024784 to serial number TU901040063438.

CURE:

If it's present the described issue in a Exprelia machine with s.n. between the above range, replace the dissolved keys.