



**Service information**

**Reference no.: SDA\_92174**

**Symptom**

The tube between flowmeter and pump in the Syntia

**Cure**

**INFO:**  
With a tube longer or shorter than 130mm can occur reduction of flow the water caused from excessive bending in the tube.

**CURE:**  
Cut the pipe with a length of 130 mm (image 1).

