



Service information

Reference no.: SDA_92181

Symptom

Latte Select DT adjustment parts

Cure

INFO:

From the field it appears there is a demand for some parts of the Drip tray height adjustment in Senseo Latte Select. After consulting with service centers, the following three parts have been added to the Bill of Material.

CURE:

The following components are now available as spare parts:

- 422224757031 DT Profile disc
- 422224759992 DT Shaft
- 422224760002 DT Gear

Also the manuals have been updated.

REMARKS:

03-04-2012: Initial version