



**Service information**

**Reference no.: SDA\_92211**

**Symptom**

Intelial display assembly

**Cure**

INFO:  
Damage and detachment of the flat cable of the display in Intelial coffee machine.

CURE:  
During handling and assembly of components on the machine take care to not "twist" the flat cable connecting the display to the electronic board.

