



Service information

Reference no.: SDA_92211

Symptom

Intelial display assembly

Cure

INFO:
Damage and detachment of the flat cable of the display in Intelial coffee machine.

CURE:
During handling and assembly of components on the machine take care to not "twist" the flat cable connecting the display to the electronic board.

