Reference no.: SDA_96095



Service information

Symptom

New software for descaling process in the Odea V2 with slim boiler from serial number TW901249599457

Cure

Improve the process of descaling.

CURE: Starting for new software V. 04.02.01 the new descaling process has been implemented: now the descale solution clean also the

Upload always the new software available in SSC.

Attached the new descaling procedure for Odea Giro V2 and Odea GO V2: a copy has to be provided to the Consumer after this

When the machine is reprogrammed with new software, a descaling cycle must be done. The new software is going to reset all values and counters on the main board.

HISTORY: 23/07/2013 - Second review - Includes SDAs_90557 - 90856 06/12/2012 - First Release