

Service information

Symptom

Reference no.: SDA_96266

New software New Royal machines.

Cure

INFO:

Improvements in the functions and in the languages for the client in New Royal machines.

CURE:

Upload the new software SW V.00.03.07 in the New Royal machines

Added the Steam product in Special Menu Beverage
Added the Powder Killer improvement (Coffee Powder Waste): now the coffee is poured in to the dreg drawer only after Added the Powder Killer improvement (Corree Powder Waste): now the corree is poured in to the dreg drawwet
 Added warning Clean Cappuccinatore after 10 minutes from the execution of milk product
 In the double coffee product the machine grind the coffee for the second product while brew the first one.
 Improved Coffee temperature control and flow rate handler to avoid reaching high temperature in products performed very quickly (or double products) at low flow rates.
 Improved Milk temperature control: Changed the estimation of steam boiler temperature, No power for the larged start at 1400C instand 146EC, medified come ID, values.

- Improved Milk temperature control: Changed the estimation of steam boiler temperature, No power for the last 2 sec of product, preload start at 140°C instead 145°C, modified some PID values Changed the first phase of descale: now the decaling go also through the brew unit Improved the abilitation of water filter: now is possible to abilitate the water filter only through the activation process Removed SWISS parameter: now the Ecomode is ON by default Added the following new phrases: CAPPUCCINATORE RINSING STOP STEAM VES

YES NO START CLEANING

WARNING CLEANING STOP CLEANING REPLACE MILK CONTAINER WITH ANOTHER ONE WITH FRESH WATER

Improved Russian language