



**Service information**

**Reference no.: SDA\_97067**

**Symptom**

Thermostat fuse break

**Cure**

**INFO:**

New software to avoid the thermostat fuse break and to improve by increasing the time before descale request.

**CURE:**

Upload the new software V. 00.01.00

**In Detail:**

- avoid the thermostat fuse break.
- Update descale : better count of descale impulses for steam.

**History:**

27-03-14: First review - Changed symptom description.

18-02-13: First release