



Service information

Reference no.: SDA_97341

Symptom

New descaling process in the Xelsis Family.

Cure

INFO:
Improve the process of descaling.

CURE:
Starting from each software of each model in this following list the new descaling process has been implemented: now the descale solution clean also the pin boiler.

XELSIS CLASS:

- SW V.01.03.01 for machine up to S/N TU901150186483 with Old Standard Boiler
- SW V.01.04.13 for machine from S/N TU901150186484 with Slim Boiler

XELSIS FOCUS:

- SW V.01.07.01

XELSIS ID:

- SW V.02.07.03

Uploaded always the new software available in SSC.

Note:

When the machine is reprogrammed with new software, a descaling cycle must be done. The new software is going to reset all values and counters on the main board.

HISTORY:

31/05/2013 - Second review – Includes SDAs_90856 - 90557 - 95395
11/03/2013 - First Release