



Service information

Reference no.: SDA_97893

Symptom

Sealing flatcable of the Displaypanel

Cure

INFO:

The sealing around the flatcable of the Display panels of all Grind & Brew appliances is insufficient to keep out steam. When steam (possibly in combination with Acetic acid) comes into the display panel it is more likely to become defective.

CURE:

As an interim solution we request the service center to apply an Acrylic sealant (422245956181) around the opening where the flatcable enters the Display panel.

The supplier installed a 100% check in production for proper sealing of the Display panel, so sets from WK1314 onwards will no longer show large gaps around this area.

REMARKS:

17-04-2013: Initial version