



Service information

Reference no.: SDA_98235

Symptom

Scattered ground coffee inside the appliance

Cure

INFO:

In the field we see a lot of appliances coming back which are badly contaminated with coarse ground coffee. This is caused by the gap between the bean container and the grinder itself. The gap allows ground coffee to rebound from the grinder and then spill inside the appliance.

CURE:

Place a seal (996510064766) on top of the grinder.

REMARKS:

07-05-2013: Initial version