

Service Service Service



Philips Consumer Lifestyle

Service Manual

PRODUCT INFORMATION

- Product meets the requirements regarding interference suppression on radio and television.
- After the product has been repaired, it should function properly and has to meet the safety requirements as laid down officially established at this moment.

TECHNICAL INFORMATION

Voltage:	120-127V
Frequency:	50-60Hz
Speeds:	2+ pulse
Blender working capacity:	1.75L
Bowl working capacity flour:	500g
Bowl working capacity dry:	1.2L
Bowl working capacity liquid:	2.1L
Mini chopper capacity:	250ml
Power cord length:	1m
Motor unit:	Variospeed
Function buttons:	Pulse, Ice
Safety:	Lid & bowl detection, Mechanical 1.5sec brake
Color:	White (RI7761, RI7762/0x) Black (RI7762/9x)

DISASSEMBLY-AND RE-ASSEMBLE ADVISE

- No specific issues.













REPAIR INSTRUCTION

- No specific issues.





ACCESSORIES

- See exploded view for more information

EXPLODED VIEW & PARTLIST (ACCESSORIES)



EXPLODED VIEW & PARTLIST (MAIN UNIT)



Partlist for Accessories

Pos	Service Code	Description	Remark
1	9965 100 51802	JAR LID STAR WHITE	
	9965 100 52991	JAR LID BLACK	FOR RI7762/90, RI7762/91
2	9965 100 51807	BLENDER JAR	
3	9965 100 51815	BLENDER CAP	
4	9965 100 51798	MINI CHOPPER STAR WHITE	
	9965 100 52997	MINI CHOPPER BLACK	FOR RI7762/90, RI7762/91
5	9965 100 59182	SEALING RING + BLENDER KNIFE	
6	9965 100 51804	PUSHER	
7	9965 100 60717	BOWL,BOWL LID&TOOL HOLDER	
	9965 100 60716	BOWL,BOWL LID&TOOL HOLDER BLACK	FOR RI7762/90, RI7762/91
9	9965 100 51806	SPATULA STAR WHITE	
	9965 100 52998	SPATULA BLACK	FOR RI7762/90, RI7762/91
11	9965 100 51816	KNEADING ACCESSORY	
12	9965 100 51808	BLADE UNIT	
13	9965 100 51796	EMULSIFYING DISC	
14	9965 100 51828	COARSE SLICING	FOR RI7762 ONLY
15	9965 100 51826	FINE SLICING	FOR RI7762 ONLY
16	9965 100 51832	CHIP DISC	FOR RI7762 ONLY
17	9965 100 51829	GRANULATING DISC	FOR RI7762 ONLY
18	9965 100 51831	ACCESSORY STORAGE TRAY	FOR RI7762 ONLY
19	9965 100 51825	PLASTIC INSERT HOLDER	FOR RI7761 ONLY
20	9965 100 51817	FINE SHREDDING DISC	FOR RI7761 ONLY
21	9965 100 51794	COARSE SHREDDING DISC	FOR RI7761 ONLY
22	9965 100 51819	GRANULATING DISC	FOR RI7761 ONLY
23	9965 100 51818	SLICING DISC 1.2MM	FOR RI7761 ONLY
24	9965 100 51812	SLICING DISC 2.4MM	FOR RI7761 ONLY

Partlist for Main Unit

Pos	Service Code	Description	Remark
25A	9965 100 51799	HOUSING ASSY OYSTER METALLIC	
25B	9965 100 51827	HOUSING ASSY BLACK	FOR RI7762/90, RI7762/91
26A	9965 100 51809	BOTTOM ASSY OYSTER METALLIC	
26B	9965 100 51833	BOTTOM ASSY BLACK	FOR RI7762/90, RI7762/91
27	9965 100 51814	SUCKER FOOT (1PC)	
28A	9965 100 51821	MOTOR INCL. WIRES + GEAR BOX (220-240V)	FOR RI7761/01, RI7762/01, RI7762/91
28B	9965 100 52425	MOTOR INCL. WIRES + GEAR BOX (120-127V)	FOR RI7761/00, RI7762/00, RI7762/90
29	9965 100 51795	MICRO SWITCH + SWITCH HOLDER	
30	9965 100 51805	SWITCH ASSY	
31	9965 100 51822	CORD STORAGE	
32	9965 100 51811	CORDSET BR WHITE	FOR BRAZIL
	9965 100 52999	CORDSET BR BLACK	FOR RI7762/90, RI7762/91

Revision list

1. Version 1.3, making parts 7,8 and 10 as one spare part(7) for the matching issue.
2. Version 1.4, correct supplier's wrong factory code issue for position 5, so the service code for position 5 changed.
3. Version 1.5, Spray paint handle cover & lid cap changed from spray paint to in-mould color, so the position 7 service code changed.
4. Version 1.6, modify the bowl capacity.